


From: [Garyg Miller](#)
To: [Rita Engblom](#)
Subject: Attebury Info
Date: 04/09/2008 09:51 AM

Rita - EPA does have the lead for Gulfco. TCEQ did the SSI/ESI for the HRS package - they get grants from EPA to do them & normally do most of the SSIs unless for some reason they decline - then EPA would do it with our contractors.

Later,

Gary Miller
Remediation Project Manager
EPA Region 6 - Superfund (6SF-RA)
(214) 665-8318
miller.garyg@epa.gov

▼ [Rita Engblom/R6/USEPA/US](#)

Rita Engblom/R6/USEPA/US
To: Garyg Miller/R6/USEPA/US@EPA
cc
04/08/2008 11:46 AM
Subject: Re: 

Looking back I found this email from you - it provides the information I was looking for on tanks. Thanks.

I wanted to confirm - you said EPA is the lead for this site.. I'm assuming TCEQ was previously the lead when they conducted the SSI and ESI. Is that correct?

Rita Engblom
1445 Ross Avenue (6SF-PR)
Dallas, TX 75202

214-665-8341 (work)
214-789-2302 (cell)
214-665-7447 (fax)

▼ [Garyg Miller/R6/USEPA/US](#)

Garyg Miller/R6/USEPA/US
To: Rita Engblom/R6/USEPA/US@EPA, Barbara Nann/R6/USEPA/US@EPA

02/14/2008 12:43 PM

cc Donald Williams/R6/USEPA/US@EPA
Subject

Folks,

I've summarized the available info on the Gulfco above ground storage tanks in the file below. Some of the tanks contain hazardous chemicals, some contain hydrocarbons, some have a mix, & some are empty. The question is, which ones fit the requirements for the CERCLA removal authority (ISE), & which ones don't? If not CERCLA then some other authority for the hydrocarbons? The tanks are generally in a poor condition with corrosion, some leaks, etc. I would appreciate any thoughts you might have on this. FYI, the information w/o dates is recent (2007), and the information preceded by 1999 is from a site inspection that LDL commissioned in 1999.

Thanks,

Gary Miller
Remediation Project Manager
EPA Region 6 - Superfund (6SF-RA)
(214) 665-8318
miller.garyg@epa.gov

[attachment "Gulfco Tank Summary 2-13-08.xls" deleted by Garyg Miller/R6/USEPA/US]